































RV

























REFRIGERATOR		
STOVE		
MICROWAVE		
A/C SYSTEM		
FAUCETS		
BLACK WATER TANK		
GRAY WATER TANK		
WATER HEATER		
WATER LEAKS		
BATHROOMS		
BEDROOMS		
LIGHTING	One of the interior lights does not work.	
GENERATOR		
SLIDE OUTS		
AWNING		

VEHICLE INFO
























YEAR	2005
MAKE	Tiffin
MODEL	Allegro Bus
MILEAGE	48606
TRANSMISSION	Automatic
VIN NUMBER	4uzabfcy75cv07773
INTERIOR	Vinyl
INTERIOR COLOR	Tan
BODY COLOR	Tan
ENGINE	6 Cylinder
DRIVE TYPE	Rear Wheel Drive
FUEL TYPE	Diesel

EXTERIOR		
BACK-UP CAMERA		
WIPER BLADES		
WINDSHIELD WASHER		
BODY ALIGNMENT	The two lower panels on the left side are misaligned.	
SCRATCHES	There are scratches along the left side and right side.	
DINGS	There are approximately three dings on the right side.	
DENTS		
PAINT CONDITION	The paint condition is good overall with clear coat peeling here and there. There is a panel on the right side to where the red doesn't match the panel next to it. There are also two panels on the left rear that have paint runs.	
BODY SEALS		
RUST		
EXTERIOR LIGHTS	The headlights are worn and foggy due to oxidization. The right rear taillight housing has scratches.	
DOOR MIRRORS	The left mirror base has chrome peeling.	
SIDE MOLDINGS	The clear coat is peeling on the left side moldings.	
FRAME DAMAGE		
GLASS		

INTERIOR

STEERING WHEEL		
HORN		
CRUISE CONTROL		
SEAT CONDITION	There is light wear to the seats. Normal for mileage.	
SEAT BELTS		
CLOCK		
RADIO/NAVIGATION		
INNER DOOR PANELS		
POWER LOCKS		
WINDOW FUNCTION		
CENTER CONSOLE		
DASH		
SUN VISORS		
DASH LIGHTS		
DASH GAUGES		
AIR CONDITIONING		
HEATER		
CARPET	The carpets are dirty.	
CIGARETTE USE		
UNUSUAL ODORS		
CUP HOLDERS		
HEADLINER		
BLOWER MOTOR		
INTERIOR TRIM	The interior trim shows normal wear consistent with age and mileage.	

MECHANICAL

AIR FILTER	
BATTERY CONDITION	
CHARGING SYSTEM	
COOLING FAN CONDITION	
RADIATOR CAP SEALING PROPERLY	
HOSES	
RADIATOR	
ENGINE COOLANT	
COOLANT LEAKS	
BELTS	
POWER STEERING	
STEERING FLUID	
ENGINE OIL	
ENGINE FLUID LEAKS	
TRANSMISSION FLUID	
TRANSMISSION LEAKS	
BRAKE SYSTEM	
DIFFERENTIAL LEAKS	
MUFFLER SYSTEM	
CV JOINTS AND AXLES	
SHOCKS AND BUSHINGS	
BALL JOINTS AND TIE RODS	
KEY FOB	

ROAD TEST

ENGINE PERFORMANCE



TRANSMISSION PERFORMANCE



DIFFERENTIAL PERFORMANCE



WHEEL BEARING PERFORMANCE



BRAKING PERFORMANCE



SUSPENSION PERFORMANCE



STEERING PERFORMANCE



ENGINE STARTING



COMPUTER DIAGNOSIS/OBD2



Computer system scanned: no problems with current or pending codes. No problems with live data. It is possible for some sneaky sellers to erase codes before we arrive, in which case some issues may be hidden.