

Report #479988

1966 Pontiac GTO



Summary

This 1966 Pontiac GTO is a very nice vehicle. When you walk up on it the first things you notice is how all the parts are nicely square on the frame an you don't notice anything is missing or broken. When you walk up on the front of the vehicle you will notice that there is some paint cracking in the front tip of the bonnet, its only a few spots, but there is some. The paint on the exterior of this vehicle does have some swirl marks in it, an by no means is this vehicle 100% show quality ready, but it still looks really nice if you don't really care too much about the swirls in the paint outer top coat. I did not find any kind of small ding or dent in the exterior of the vehicle. While walking around it looks to be that all the correct parts are on the vehicle for the period an date of while the vehicle is from.

The engine in this vehicle looks really nice an seems to be well kept. The owner has some done some suspension work on the vehicle showing that it has some newer suspension components. The owner has converted the vehicle to front disc brakes as apposed to the drum brakes that were on the vehicle prior to his ownership of the vehicle.

Now during the test drive of the vehicle it went really nicely! It was a very smooth ride an shifted thru all the gears very nicely. Accelerated really well an seemed to have plenty of power for all your American muscle needs. The handling is really nice an feels nice an tight, its not bumpy or sloppy in any way an feels as if were to have just come from the factory. Under the vehicle i could not find any kind of major rust issues at all, though I did seem to find some very light surface rust on some of the parts that the under coating has come off of. the vehicle owner has told me that he had the squareness of the vehicle tested an it was 100% square which is really rare among the convertibles of this era. This vehicle sounds really nice an runs really well also. Overall this 1966 GTO is a nice vehicle.

See below and pictures for more info











Vehicle Information

Year	1966
Make	Pontiac
Model	GTO
VIN	242676B121921
Stock No.	n/a
Mileage	14197
Engine Cylinders	8 Cylinder
Exterior Color	Maroon
Interior Color	Red
Interior Material	Vinyl
Engine Number	n/a
Transmission Number	n/a
Fuel Type	Gas

Drivetrain

Transmission	Manual
Drive Type	Rear Wheel Drive

Road Test

Road Test	 Good
Engine Starting Easily	 Good
Engine running well after Started	 Good
Transmission performance	 Good
Clutch Performance	 Good
Differential Performance	 Good
Wheel Bearing Performance	 Good
Braking Performance	 Good
Suspension Performance	 Good
Steering Performance and Alignment	 Good

Exterior

Wiper Blades	■ Issues
--------------	----------

Wipers do not function

Body Panel Alignment	■ Good
----------------------	--------

Scratches	■ Issues
-----------	----------

There are numerous swirl marks all over the vehicle

Paint Condition	■ Issues
-----------------	----------

The paint has some spots that are cracked on the paint, shown in photos

Seals	■ Good
-------	--------

Rust	■ Issues
------	----------

Some very very light surface rust on some of the under chassis parts.

Exterior Lights	■ Good
-----------------	--------

Power Door Mirrors	■ Good
--------------------	--------

Bumpers	■ Good
---------	--------

Side Moldings	■ Good
---------------	--------

Convertible Top	■ Good
-----------------	--------

Underbody/Frame Condition	■ Good
---------------------------	--------

Glass	■ Good
-------	--------

Floors	■ Good
--------	--------

Rockers	■ Good
---------	--------

Quarter Panels	■ Good
----------------	--------

Hood	■ Good
------	--------

Doors	■ Good
-------	--------

Dings	■ Good
-------	--------

Dents	■ Good
-------	--------

Chrome	■ Good
--------	--------

Interior

Steering Wheel	■ Good
----------------	--------

Horn	■ Good
------	--------

Seat Condition	■ Good
----------------	--------

Seat Belts	■ Good
------------	--------

Clock	■ Good
-------	--------

Radio/Navigation/DVD	■ Issues
----------------------	----------

Does not work

Inner Door Panels	■ Good
-------------------	--------

Center Console	■ Good
----------------	--------

Dash	■ Issues
------	----------

The dash is showing wear and tear consistent with the age of the vehicle.

Dash Lights Working	■ Good
---------------------	--------

Heater	■ Issues
--------	----------

Does not work

Carpet	■ Good
--------	--------

Floor Mats	■ Good
------------	--------

Blower Motor	■ Issues
--------------	----------

Does not work

Instrument Cluster/Gauges	■ Good
---------------------------	--------

Window Function	■ Good
-----------------	--------

Interior Trim	■ Good
---------------	--------

Sun Visors	■ Good
------------	--------

Mechanical

Air Filter	■ Good
Battery Condition	■ Good
Charging System	■ Good
Cooling Fan Condition Mechanical/Electronic	■ Good
Hoses and Clamps Age/Cracking	■ Good
Radiator Condition	■ Good
Engine Coolant Condition	■ Good
Belts	■ Good
Power Steering System	■ Good
Power Steering Fluid Condition	■ Good
Engine Oil Condition	■ Good
Transmission Fluid Condition	■ Good
Brake System Condition	■ Good
Muffler System	■ Good
CV Boots and Joints	■ Good
Shocks and bushings Condition. Leaking?	■ Good
Ball Joints and Tie Rods	■ Good
Radiator Cap Sealing Properly	■ Good

Tire / Wheels

Manufacturer	
Driver's Front Tire	Cooper Cobra
Passenger's Front Tire	Cooper Cobra
Driver's 1st Axle Outer Tire	Cooper Cobra
Passenger's 1st Axle Outer Tire	Cooper Cobra
Size	
Driver's Front Tire	235/60/14
Passenger's Front Tire	235/60/14
Driver's 1st Axle Outer Tire	235/60/14
Passenger's 1st Axle Outer Tire	235/60/14
Tire Condition	
Driver's Front Tire	No Issues
Passenger's Front Tire	No Issues
Driver's 1st Axle Outer Tire	No Issues
Passenger's 1st Axle Outer Tire	No Issues
Wheel Condition	
Driver's Front Tire	Scratches
Driver's 1st Axle Outer Tire	Scratches
Passenger's Front Tire	Scratches
Passenger's 1st Axle Outer Tire	Scratches
Tire Tread	
Driver's Front Tire	9/32
Passenger's Front Tire	9/32
Driver's 1st Axle Outer Tire	8/32
Passenger's 1st Axle Outer Tire	8/32
Spare Tire	Yes

Vehicle Images

